

EXHIBIT L

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 1 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

BY: VOLKERT, INC.	STRUCTURE NAME: STRUCTURE B SANIBEL CAUSEWAY
OWNER: 2 County Hwy Agency	YEAR BUILT: 2007
MAINTAINED BY: 2 County Hwy Agency	SECTION NO.: 12 000 000
STRUCTURE TYPE: 6 P/S Conc Continuous - 02 Stringer/Girder	MP: 0
LOCATION: 2ND STRUCTURES OF TOLL PLAZA	ROUTE: 00867
SERVICE TYPE ON: 1 Highway	FACILITY CARRIED: CR-867
SERV TYPE UND: 5 Waterway	FEATURE INTERSECTED: SAN CARLOS BAY

FUNCTIONALLY OBSOLETE STRUCTURALLY DEFICIENT

TYPE OF INSPECTION: Regular NBI

DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 11/16/2011 UNDERWATER: 10/26/2011

SUFFICIENCY RATING: 79.0
HEALTH INDEX: 99.30

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 2 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

BY: VOLKERT, INC.
OWNER: 2 County Hwy Agency
MAINTAINED BY: 2 County Hwy Agency
STRUCTURE TYPE: 6 P/S Conc Continuous - 02 Stringer/Girder
LOCATION: 2ND STRUC S OF TOLL PLAZA
SERVICE TYPE ON: 1 Highway
SERV TYPE UND: 5 Waterway

STRUCTURE NAME: STRUCTURE B SANIBEL CAUSEWAY
YEAR BUILT: 2007
SECTION NO.: 12 000 000
MP: 0
ROUTE: 00867
FACILITY CARRIED: CR-867
FEATURE INTERSECTED: SAN CARLOS BAY

- THIS BRIDGE CONTAINS FRACTURE CRITICAL COMPONENTS
- THIS BRIDGE IS SCOUR CRITICAL
- THIS REPORT IDENTIFIES DEFICIENCIES WHICH REQUIRE PROMPT CORRECTIVE ACTION
- FUNCTIONALLY OBSOLETE STRUCTURALLY DEFICIENT

TYPE OF INSPECTION: Regular NBI

DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 11/16/2011 UNDERWATER: 10/26/2011

SMART FLAGS:

OVERALL NBI RATINGS:

None	DECK: 7 Good	CHANNEL: 7 Minor Damage
	SUPERSTRUCTURE: 7 Good	CULVERT: N N/A (NBI)
	SUBSTRUCTURE: 8 Very Good	SUFF. RATING: 79.0
	PERF. RATING: Good	HEALTH INDEX: 99.30

FIELD PERSONNEL / TITLE / NUMBER

INITIALS

Bibelhauser, Anthony - Bridge Inspector (CBI #00359) (lead)

Eorgan, Steve - Bridge Inspector (CBI#00362)

Hoogland, Keith - Bridge Inspector/Diver (CBI#00341) (lead)

Tumaniszwili, Alex P. - Diver/Inspector


Young, Ryan C. - Diver/Inspector

REVIEWING BRIDGE INSPECTION SUPERVISOR:

Rucks, Edward - CBI (#00273)

CONFIRMING REGISTERED PROFESSIONAL ENGINEER:

Teal, Daniel - PROJECT MANAGER (PE # 42097)
VOLKERT, INC.
3409 W. LEMON STREET STE 1
CERTIFICATE OF AUTHORIZATION NO 48415
TAMPA, FL 33609



SIGNATURE: _____

DATE: _____

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 3 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 DECKS

ELEMENT/ENV: 12/4 Bare Concrete Deck 80684 sf. ELEM CATEGORY: Decks/Slabs

CONDITION STATE (5)	DESCRIPTION	QUANTITY
1	The surface and underside of the deck have few repaired areas, there are few spalls/delaminations in the deck surface or underside and the only cracking is superficial or surface map cracking. The combined distressed area is 2% or less of the deck area.	80684 sf.

ELEMENT INSPECTION NOTES:

Note: Two 4-1/2in. diameter fiberglass conduits and one 3-1/2in. diameter PVC conduit are suspended from hangers anchored to the underside of Bay 1 in all spans. The type of anchorage for the utility hangers is unknown.

CS1: There is a light accumulation of dirt and debris in the shoulder areas.

The deck top has transverse and diagonal cracks up to 1/64in wide throughout and isolated areas of map cracking less than 1/64in wide - NEW.

The undersides of the overhangs have full width x up to 1/64in. wide transverse cracks, some with efflorescence.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 4 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 DECKS

ELEMENT/ENV: 300/4 Strip Seal Exp Joint 216 lf. ELEM CATEGORY: Joints

CONDITION STATE (3)	DESCRIPTION	QUANTITY
1	The element shows minimal deterioration. There is no leakage at any point along the joint. Gland is secure and has no defects. Debris in joint is not causing any problems. The adjacent deck and/or header is sound.	216 lf.

ELEMENT INSPECTION NOTES:

Note: Joints are at Abutments 1 and 14 and Piers 4, 7 and 10.

CS1: The joints are filling with dirt and debris, but are functioning as intended at this time.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 5 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 DECKS

ELEMENT/ENV: 334/4 Metal Rail Coated 3744 lf. ELEM CATEGORY: Railing

CONDITION STATE (5)	DESCRIPTION	QUANTITY
1	There is no evidence of active corrosion. Protective coating is sound and functioning as intended to protect the element.	3684 lf.
2	There is little or no active corrosion. Surface corrosion has formed or is forming. Protective coating may have minor areas of deterioration.	60 lf.

ELEMENT INSPECTION NOTES:

Note: Barriers meet NCHRP TL4 criteria and meet SIA Item #36 standards.

CS2: The rail to post attachment hardware has light surface corrosion on approximately half of the posts - NEW. Refer to Photo 1. REPAIR

Post 1-5 right is missing both lower rail to post attachment nuts and the top two nuts are loose - NEW. Refer to Photo 2. REPAIR

Post 11-8 right is missing one of the lower rail to post attachment nuts - NEW. REPAIR

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 6 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 SUPERSTRUCTURE

ELEMENT/ENV: 109/4 P/S Conc Open Girder 7488 lf. ELEM CATEGORY: Superstructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. There may be discoloration efflorescence, and/or superficial cracking but without affect on strength and/or serviceability.	7488 lf.

ELEMENT INSPECTION NOTES:

CS1: The beams have multiple hairline diagonal cracks in the lower flange and web up to 8ft. long near the bearing areas, extending up and away from the supports - INCREASED. These cracks vary in length number of cracks and exact location and are predominately in the exterior beams. The cracks on Beam 12-1 were marked with a red paint stick to track the general trend in crack lengths. Refer to Photo 3.

The bottom flanges of the exterior beams typically have short hairline horizontal cracks up to 2ft long throughout the length - NEW.

Several of the poured beam end diaphragms have delaminations up to 10in x 8in - INCREASED.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 7 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 SUPERSTRUCTURE

ELEMENT/ENV: 310/4 Elastomeric Bearing 104 ea. ELEM CATEGORY: Bearings

CONDITION STATE (3)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. Shear deformations are correct for existing temperatures.	104 ea.

**FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM**

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 8 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 SUBSTRUCTURE

ELEMENT/ENV: 205/4 R/Conc Column 24 ea. ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. There may be discoloration, efflorescence, and/or superficial cracking but without affect on strength and/or serviceability.	24 ea.

ELEMENT/ENV: 207/4 P/S Conc Holl Pile 180 ea. ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. There may be discoloration, efflorescence, and/or superficial cracking but without affect on strength and/or serviceability.	180 ea.

ELEMENT/ENV: 215/4 R/Conc Abutment 70 lf. ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. There may be discoloration, efflorescence, and/or superficial cracking but without affect on strength and/or serviceability.	70 lf.

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

**FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM**

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 9 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 SUBSTRUCTURE

ELEMENT/ENV: 220/4 R/C Sub Pile Cap/Ftg 12 ea. ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. There may be discoloration, efflorescence, and/or superficial cracking but without affect on strength and/or serviceability.	12 ea.

ELEMENT/ENV: 234/4 R/Conc Cap 518 lf. ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The element shows little or no deterioration. There may be discoloration, efflorescence, and/or superficial cracking but without affect on strength and/or serviceability.	518lf.

ELEMENT/ENV: 393/4 Bikhhd Sewl Any Mater 480 ft ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	There is little or no deterioration. Surface defects only are in evidence. Random open joints may exist.	480 ft

ELEMENT INSPECTION NOTES:

Note: The element represents the bulkheads constructed with concrete sheet piling and concrete caps.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 10 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 SUBSTRUCTURE

ELEMENT/ENV: 396/4 Other Abut Slope Pro 1800 sf. ELEM CATEGORY: Substructure

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	There is little or no deterioration. Surface defects only are in evidence. Random open joints may exist.	1760 sf.
2	There may be minor deterioration, random open joints, cracking and weathering. Mortar in joints may show minor deterioration.	40 sf.

ELEMENT INSPECTION NOTES:

Note: This element represents the concrete block mat slope protection.

CS2: The south slope protection is intermittently undermined up to 18in wide x 10in deep along the bulkhead cap - NEW. Refer to Photo 4. REPAIR

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 11 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 CHANNEL

ELEMENT/ENV: 290/4 Channel

1 ea.

ELEM CATEGORY: Channel

CONDITION STATE (4)	DESCRIPTION	QUANTITY
2	Bank protection is in need of minor repairs, bank may be beginning to slump, minor stream bed movement may be evident or debris may be present.	1 ea.

ELEMENT INSPECTION NOTES:

The following was noted by the underwater inspectors:

CS2: Some piles have scour holes around them up to 18in. deep.

The groundline slopes up to 4ft. to the west side of the piling and 10ft. out from the piling on several bents.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 12 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ

All Elements

UNIT: Structure Unit 1 MISCELLANEOUS

ELEMENT/ENV: 321/4 R/Conc Approach Slab 2 ea. ELEM CATEGORY: Other Elements

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	The slab has not settled and shows no sign of deterioration other than superficial surface cracks.	2 ea.

ELEMENT INSPECTION NOTES:

Note: The approach slabs are not visible due to an overlay of asphalt.

CS1: The north and south approach slab joint headers have up to a 1/32in. wide longitudinal crack.

ELEMENT/ENV: 478/4 MSE Walls 120 lf. ELEM CATEGORY: Other Elements

CONDITION STATE (4)	DESCRIPTION	QUANTITY
1	There is little or no deterioration. Surface defects only are in evidence.	120 lf.

ELEMENT INSPECTION NOTES:

Note: The MSE walls were measured back 30ft. at each corner of the structure.

Structure Notes

BRIDGE OWNER: LEE COUNTY

TRAFFIC RESTRICTIONS: Based on the load rating dated 4/21/04, the structure does not require posting. This structure is not posted.

Structure was inventoried from south to north.

This structure replaced Bridge No. 124042.

Power boat with fathometer used for underbridge inspection and groundline measurements.

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

**FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM**

Inspection/CID Report with PDF attachment(s)

**BRIDGE ID: 124115
DISTRICT: 01 Bartow**

**PAGE: 13 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ**

INSPECTION NOTES: ZOMJ 11/16/2011

Sufficiency Rating Calculation Accepted by kn110ku-P at 2011-12-13 11:14:44
Sufficiency Rating Calculation Accepted by KNVOLFA-P at 2011-12-06 11:15:13

LOAD CAPACITY EVALUATION:

The findings of this inspection reveal no reason to warrant a new analysis; therefore, the current load rating dated 4/21/04 results still govern.

The NBI Rating for SIA Item 58, Deck, was lowered from 8 to 7 due to the cracking on the deck top.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 14 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ



PHOTO 1: 334 METAL RAIL COATED

Light surface corrosion on bridge rail to post hardware.

REPAIR RECOMMENDATION:

Spot paint bridge rail to post hardware throughout both bridge rails.

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 15 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ




PHOTO 2: 334 METAL RAIL COATED

Missing bridge rail to post attachment nuts.

REPAIR RECOMMENDATION:

Replace missing rail to post attachment nuts on bridge rail posts 1-5 and 11-8 right and tighten loose nuts on post 1-5.

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 16 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ



PHOTO 3: 109 P/S CONC OPEN GIRDER

Typical diagonal cracks in the exterior beams (Beam 2-1 marked in red shown).

REPAIR RECOMMENDATION:
None

FLORIDA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)

BRIDGE ID: 124115
DISTRICT: 01 Bartow

PAGE: 17 OF 23
INSPECTION DATE: 11/16/2011 ZOMJ



PHOTO 4: 396 OTHER ABUT SLOPE PRO

Undermined block mail slope protection along the south bulkhead cap.

REPAIR RECOMMENDATION:

Fill in undermining under south slope protection along the south bulkhead cap.

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

FL DA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

Inspection/CID Report with PDF attachment(s)
COMPREHENSIVE

REPORT ID: INVT001A
Structure ID: 124115

Page 18 of 23
DATE PRINTED: 12/28/2011

Description

Structure Unit Identification

Bridge/Unit Key: 124115 1
Structure Name: STRUCTURE B SANIBEL CAUSEWAY
Description:
Type: M Main

Roadway Identification:

NBI Structure No (8) 124115
Position/Prefix (5) Route On Structure
Kind Hwy (Rte Prefix) 4 County Hwy
Design Level of Service 1 Mainline
Route Number/Suffix 00867/ 0 N/A (NBI)
Feature Intersect (6) SAN CARLOS BAY
Critical Facility Not Defense-crit
Facility Carried (7) CR-867
Mile Point (11) 0
Latitude (16) 026d28'19" Long (17) 082d01'40"

Roadway Traffic and Accidents

Lanes (28) 2	Medians 0	Speed 35 mph
ADT Class ADT Class 4		
Recent ADT (29) 19690	Year (30) 2011	
Future ADT (114) 20675	Year (115) 2031	
Truck % ADT (109) 7		
Detour Length (19) 99 mi		
Detour Speed 0 mph		
Accident Count -1	Rate -1	

Roadway Classification

Nat. Hwy Sys (104) 0 Not on NHS
National base Net (12) Not on Base Network
LRS Inventory Rte (13a) 12 000 000 Sub Rte (13b) 00
Functional Class (26) 16 Urban Minor Arterial
On Federal Aid System Y
Defense Hwy (100) 0 Not a STRAHNET hwy
Direction of Traffic (102) 2 2-way traffic
Emergency

Roadway Clearances

Vertical (10) 99.9 ft	Appr. Road (32) 40
Horiz. (47) 40 ft	Roadway (51) 40 ft
Truck Network (110) 0 Not part of natl netwo	
Toll Facility (20) 2 On toll road	
Fed. Lands Hwy (105) 0 N/A (NBI)	
School Bus Route <input checked="" type="checkbox"/>	
Transit Route <input checked="" type="checkbox"/>	

FL DA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM
Inspection/CID Report with PDF attachment(s)
COMPREHENSIVE

REPORT ID: INVT001A
Structure ID: 124115

Page 19 of 23
DATE PRINTED: 12/28/2011

Structure Identification

Admin Area Lee County
District (2) D1 - Bartow
County (3) (12) Lee
Place Code (4) Sanibel
Location (9) 2ND STRUC S OF TOLL PLAZA
Border Br St/Reg (98) Not Applicable (P) Share 0 %
Border Struct No (99)
FIPS State/Region (1) 12 Florida Region 4-Atlanta
NBIS Bridge Len (112) Meets NBI Length
Parallel Structure (101) No || bridge exists
Temp. Structure (103) Not Applicable (P)
Maint. Resp. (21) 2 County Hwy Agency
Owner (22) 2 County Hwy Agency
Historic Signif. (37) 5 Not eligible for NRHP

Structure Type and Material

Curb/Sidewalk (50): Left 0 ft Right 0 ft
Bridge Median (33): 0 No median
Main Span Material (43A): 6 P/S Conc Continuous
Appr Span Material (44A): Not Applicable (P)
Main Span Design (43B): 02 Stringer/Girder
Appr Span Design (44B): Not Applicable (P)

Geometrics

Spans in Main Unit (45) 13
Approach Spans (46) 0
Length of Max Span (48) 144 ft
Structure Length (49) 1872 ft
Total Length 1912 ft
Deck Area 80684 sqft
Structure Flared (35) 0 No flare

Age and Service

Year Built (27) 2007
Year Reconstructed (106) 0
Type of Service On (42a) 1 Highway
Under (42b) 5 Waterway
Fracture Critical Details Not Applicable

Deck Type and Material

Deck Width (52): 43.1
Skew (34): 0
Deck Type (107): 1 Concrete-Cast-in-Place
Surface (108): 0 None
Membrane: 0 None
Deck Protection: None

Appraisal

Structure Appraisal

Open/Posted/Closed (41) A Open, no restriction
Deck Geometry (68) 5 Above Tolerable
Underclearances (69) N Not applicable (NBI)
Approach Alignment (72) 8-No Speed Red thru Curv
Bridge Railings (36a) 1 Meets Standards
Transitions (36b) 1 Meets Standards
Approach Guardrail (36c) 1 Meets Standards
Approach Guardrail ends (36d) 1 Meets Standards
Scour Critical (113) 8 Stable Above Footing

Navigation Data

Navigation Control (38) Permit Required
Nav Vertical Clr (39) 13.5 ft
Nav Horizontal Clr (40) 110 ft
Min Vert Lift Clr (116) 0 ft
Pier Protection (111) 1 Not Required

NBI Condition Rating

Sufficiency Rating 79
Health Index 99.3
Structural Eval (67) 7 Above Min Criteria
Deficiency Not Deficient

Minimum Vertical Clearance

Over Structure (53) 99.99 ft
Under (reference) (54a) N Feature not hwy or RR
Under (54b) 0 ft

Minimum Lateral Underclearance

Reference (55a) N Feature not hwy or RR
Right Side (55b) 0 ft
Left Side (56) 0 ft

Load Rating

Design Load (31) HL 93
Rating Date 4/21/2004 Initials MCM
Posting (70) 5 A/Above Legal Loads

Operating Type (63) 1 LF Load Factor
Operating rating (64) 99.9 tons Alternate -1
Inventory Type (65) 1 LF Load Factor
Inventory Rating (66) 59.2 tons Alternate -1
Alt Meth -1

Schedule

Current Inspection

Inspection Date: 11/16/2011
Inspector: KN738AB-P - Anthony Bibelhauser
Bridge Group: BD523
Primary Type: Regular NBI
Review Required:

Next Inspection Date Scheduled

NBI: 11/16/2013
Element: 11/16/2013
Fracture Critical:
Underwater: 11/16/2013
Other/Special:

FL DA DEPARTMENT OF TRANSPORTATION
 BRIDGE MANAGEMENT SYSTEM
 Inspection/CID Report with PDF attachment(s)
 COMPREHENSIVE

REPORT ID: INVT001A
 Structure ID: 124115

Page 20 of 23
 DATE PRINTED: 12/28/2011

Schedule Cont.

Inspection Types
Performed

NBI Element Fracture Critical Underwater Other Special

Inspection Intervals

Required (92)

Frequency (92)

Last Date (93)

Inspection Resources

Fracture Critical	<input type="checkbox"/>	mos		Crew Hours	10
Underwater	<input checked="" type="checkbox"/>	24 mos	10/26/2011	Flagger Hours	0
Other Special	<input type="checkbox"/>	mos		Helper Hours	0
NBI		24 mos (91)	11/16/2011 (90)	Snooper Hours	0
				Special Crew Hours	3
				Special Equip Hours	0

Custom

General Bridge Information

Parallel Bridge Seq -1

Channel Depth 22.5 ft

Radio Frequency -1

Phone Number (000) 000-0000

Exception Date

Exception Type Unknown

Accepted By Maint 00/00/0000

Warranty Expiration 00/00/0000

Bridge Rail 1 Steel barrier
 Bridge Rail 2 Not applicable-No rail
 Electrical Devices No electric service
 Culvert Type Not applicable
 Maintenance Yard 0
 FIHS ON / OFF No Routes on FIHS
 Previous Structure 124042
 2nd Previous Structure
 Replacement Structure

Bridge Load Rating Information

HS20 Govr. Span Length 144 ft

L-Rating Origination Design Plans

Load Rating Date 04/21/2004

Method Calculation Others

Load Dist. Factor 1.047

Impact Factor 19

Design Method Load Factor

Design Measure English

Recommend SU Posting 99 tons

Recommend C Posting 99 tons

Recommend ST Posting 99 tons

Gov FB Span 0 ft

Gov FB Spacing 0 ft

FB HS20 Rating 0 tons

FB SU4 Rating 0 tons

FB Present N

FB INV Rating Factor 0

FB OPR Rating Factor 0

FB FL 120 0 tons

Single Unit Truck 2 Axles 91.6 tons
 Single Unit Truck 3 Axles 76.6 tons
 Single Unit Truck 4 Axles 82.4 tons
 Combination Unit Truck 3 Axles 93.5 tons
 Combination Unit Truck 4 Axles 84.4 tons
 Combination Unit Truck 5 Axles 92.899 tons
 Truck Trailer 5 Axles 98.1 tons
 Posting Weight 99 tons
 Actual SU Posting 99 tons
 Actual C Posting 99 tons
 Actual ST Posting 99 tons
 FL 120 Long Gov Span -1 tons
 FL 120 Trans -1 tons
 Single Axle Trans -1 tons
 Tandem Axle Trans -1 tons
 Wing Span -1 ft
 Web to Web Span -1 ft
 HS20 OPR Rating Max Span 98.9 tons
 FL120 Long Max Span -1 tons

Bridge Scour and Storm Information

Pile Driving Record All pile driving records

Foundation Type Foundation details

Mode of Flow Tidal

Rating Scour Eval Low Risk - High

Highest Scour Eval No phase completed

Scour Recommended I No recommendation
 Scour Recommended II No recommendation
 Scour Recommended III No recommendation
 Scour Elevation 999 ft
 Action Elevation 999 ft
 Storm Frequency 100

Condition

NBI Rating

Channel (61) 7 Minor Damage

Deck (58) 7 Good

Superstructure (59) 7 Good

Substructure (60) 8 Very Good

Culvert (62) N/A (NBI)
 Waterway (71) 8 Equal Desirable
 Unrepaired Spalls -1 sq.ft.
 Review Required

FL: JA DEPARTMENT OF TRANSPORTATION
 BRIDGE MANAGEMENT SYSTEM
 Inspection/CID Report with PDF attachment(s)
 COMPREHENSIVE

REPORT ID: INVT001A
 Structure ID: 124115

Page 21 of 23
 DATE PRINTED: 12/28/2011

Elements

Inspection Date: 11/16/2011ZOMJ

Span Id	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	Qty5	%5	T Qty
Structure	12/4	Bare Concrete Deck	80684	100.	0	.	0	.	0	.	0	.	80684 sf.

Notes Note: Two 4-1/2in. diameter fiberglass conduits and one 3-1/2in. diameter PVC conduit are suspended from hangers anchored to the underside of Bay 1 in all spans. The type of anchorage for the utility hangers is unknown.

CS1: There is a light accumulation of dirt and debris in the shoulder areas.

The deck top has transverse and diagonal cracks up to 1/64in wide throughout and isolated areas of map cracking less than 1/64in wide - NEW.

The undersides of the overhangs have full width x up to 1/64in. wide transverse cracks, some with efflorescence.

Structure	300/4	Strip Seal Exp Joint	216	100.	0	.	0	.	0	.	0	.	216 lf.
-----------	-------	----------------------	-----	------	---	---	---	---	---	---	---	---	---------

Notes Note: Joints are at Abutments 1 and 14 and Piers 4, 7 and 10.

CS1: The joints are filling with dirt and debris, but are functioning as intended at this time.

Structure	334/4	Metal Rail Coated	3684	98.4	60	1.6	0	.	0	.	0	.	3744 lf.
-----------	-------	-------------------	------	------	----	-----	---	---	---	---	---	---	----------

Notes Note: Barriers meet NCHRP TL4 criteria and meet SIA Item #36 standards.

CS2: The rail to post attachment hardware has light surface corrosion on approximately half of the posts - NEW. Refer to Photo 1. REPAIR

Post 1-5 right is missing both lower rail to post attachment nuts and the top two nuts are loose - NEW. Refer to Photo 2. REPAIR

Post 11-8 right is missing one of the lower rail to post attachment nuts - NEW. REPAIR

Structure	109/4	P/S Conc Open Girder	7488	100.	0	.	0	.	0	.	0	.	7488 lf.
-----------	-------	----------------------	------	------	---	---	---	---	---	---	---	---	----------

Notes CS1: The beams have multiple hairline diagonal cracks in the lower flange and web up to 8ft. long near the bearing areas, extending up and away from the supports - INCREASED. These cracks vary in length number of cracks and exact location and are predominately in the exterior beams. The cracks on Beam 12-1 were marked with a red paint stick to track the general trend in crack lengths. Refer to Photo 3.

The bottom flanges of the exterior beams typically have short hairline horizontal cracks up to 2ft long throughout the length - NEW.

Several of the poured beam end diaphragms have delaminations up to 10in x 8in - INCREASED.

Structure	310/4	Elastomeric Bearing	104	100.	0	.	0	.	0	.	0	.	104 ea.
-----------	-------	---------------------	-----	------	---	---	---	---	---	---	---	---	---------

Notes

Structure	205/4	R/Conc Column	24	100.	0	.	0	.	0	.	0	.	24 ea.
-----------	-------	---------------	----	------	---	---	---	---	---	---	---	---	--------

Notes

Structure	207/4	P/S Conc Holl Pile	180	100.	0	.	0	.	0	.	0	.	180 ea.
-----------	-------	--------------------	-----	------	---	---	---	---	---	---	---	---	---------

Notes

Structure	215/4	R/Conc Abutment	70	100.	0	.	0	.	0	.	0	.	70 lf.
-----------	-------	-----------------	----	------	---	---	---	---	---	---	---	---	--------

Notes

FL DA DEPARTMENT OF TRANSPORTATION
 BRIDGE MANAGEMENT SYSTEM
 Inspection/CID Report with PDF attachment(s)
 COMPREHENSIVE

REPORT ID: INVT001A
 Structure ID: 124115

Page 22 of 23
 DATE PRINTED: 12/28/2011

Elements

Inspection Date: 11/16/2011ZOMJ

Span Id	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	Qty5	%5	T Qty
Structure	220/4	R/C Sub Pile Cap/Ftg	12	100.	0	.	0	.	0	.	0	.	12 ea.

Notes

Structure	234/4	R/Conc Cap	518	100.	0	.	0	.	0	.	0	.	518 lf.
-----------	-------	------------	-----	------	---	---	---	---	---	---	---	---	---------

Notes

Structure	393/4	Blkhd Sewl Any Mater	480	100.	0	.	0	.	0	.	0	.	480 ft
-----------	-------	----------------------	-----	------	---	---	---	---	---	---	---	---	--------

Notes Note: The element represents the bulkheads constructed with concrete sheet piling and concrete caps.

Structure	396/4	Other Abut Slope Pro	1760	97.78	40	2.22	0	.	0	.	0	.	1800 sf.
-----------	-------	----------------------	------	-------	----	------	---	---	---	---	---	---	----------

Notes Note: This element represents the concrete block mat slope protection.

CS2: The south slope protection is intermittently undermined up to 18in wide x 10in deep along the bulkhead cap - NEW. Refer to Photo 4.
 REPAIR

Structure	290/4	Channel	0	.	1	100.	0	.	0	.	0	.	1 ea.
-----------	-------	---------	---	---	---	------	---	---	---	---	---	---	-------

Notes The following was noted by the underwater inspectors:
 CS2: Some piles have scour holes around them up to 18in. deep.
 The groundline slopes up to 4ft. to the west side of the piling and 10ft. out from the piling on several bents.

Structure	321/4	R/Conc Approach Slab	2	100.	0	.	0	.	0	.	0	.	2 ea.
-----------	-------	----------------------	---	------	---	---	---	---	---	---	---	---	-------

Notes Note: The approach slabs are not visible due to an overlay of asphalt.

CS1: The north and south approach slab joint headers have up to a 1/32in. wide longitudinal crack.

Structure	478/4	MSE Walls	120	100.	0	.	0	.	0	.	0	.	120 lf.
-----------	-------	-----------	-----	------	---	---	---	---	---	---	---	---	---------

Notes Note: The MSE walls were measured back 30ft. at each corner of the structure.

Total Number of Elements: 15

Inspection Information

Inspection Date: 11.16.2011

Type: Regular NBI

Inspector: KN738AB-P - Anthony Bibelhauser

Inspection Notes: Sufficiency Rating Calculation Accepted by kn110ku-P at 2011-12-13 11:14:44
 Sufficiency Rating Calculation Accepted by KNVOLFA-P at 2011-12-06 11:15:13

LOAD CAPACITY EVALUATION:

The findings of this inspection reveal no reason to warrant a new analysis; therefore, the current load rating dated 4/21/04 results still govern.

The NBI Rating for SIA Item 58, Deck, was lowered from 8 to 7 due to the cracking on the deck top.

FL DA DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM
Inspection/CID Report with PDF attachment(s)
COMPREHENSIVE

REPORT ID: INVT001A
Structure ID: 124115

Page 23 of 23
DATE PRINTED: 12/28/2011

Structure Notes

BRIDGE OWNER: LEE COUNTY

TRAFFIC RESTRICTIONS: Based on the load rating dated 4/21/04, the structure does not require posting. This structure is not posted.

Structure was inventoried from south to north.



This structure replaced Bridge No. 124042.

Power boat with fathometer used for underbridge inspection and groundline measurements.

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM
 Bridge Profile Report

REPORT ID: INVT016
 Structure #: 124115

DATE PRINTED: 12/28/2011
 Page 1 of 3



FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM
 Bridge Profile Report

REPORT ID: INVT016
 Structure #: 124115

DATE PRINTED: 12/28/2011
 Page 2 of 3

Profile Data - Numerical Summary

(All Heights Are In Feet)

Inspection Date and Key: 11/16/2011 ZOMJ

Bent #	Left Height	Right Height
1	-1	-1
2	19	20.5
3	23.5	24
4	24.5	25.5
5	25	25.5
6	25	26
7	25	25
8	24	23
9	23.5	24
10	23.5	25
11	23	23.5
12	21	23.5
13	15	16.5
14	-1	-1

Air Temp:

Profile Notes:

Measurements referenced from the top of the footers.
 Waterline at footer 2 left and right = 3ft.
 Note: A value of -1 indicates that this location is out of the water.

Inspection Date and Key: 11/30/2009 JXNS

1	-1	-1
2	21.3	21.3
3	22.5	25
4	23.5	26
5	23.5	24.5
6	23.5	24.5
7	22.5	23
8	22.5	23.5
9	23	23
10	23	25
11	22.5	23
12	22.5	23

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM
 Bridge Profile Report

REPORT ID: INVT016
 Structure #: 124115

DATE PRINTED: 12/28/2011
 Page 3 of 3

Profile Data - Numerical Summary

Inspection Date and Key:	Bent #	Left Height	Right Height	(All Heights Are In Feet)
11/30/2009 JXNS	13	16.5	18	
	14	-1	-1	

Air Temp: 1

Profile Notes:

Measurements referenced from the top of the footers.
 Waterline at Footer 2 left and right = 3.5ft.
 Note: A value of -1 indicates that this location was out of the water during this inspection.

Inspection Date and Key: 11/15/2007 NRSE

1	-1	-1	-1
2	17.2	17.8	17.8
3	19.4	21.3	21.3
4	20.5	24.1	24.1
5	21	21.9	21.9
6	21.2	20.8	20.8
7	20.4	19.9	19.9
8	19.8	20.3	20.3
9	19.3	22.1	22.1
10	19.8	21.6	21.6
11	20.1	20.5	20.5
12	19	20.2	20.2
13	12.6	14	14
14	-1	-1	-1

Air Temp:

Profile Notes:

Profile Reference: Top of footer 2
 Waterline to top of footer 2: 2.2ft Left and Right

